






FIG. 1 FIG. 2















FIG. 8



|                             | 112   |
|-----------------------------|---|
| Scaffold Information System | Trade Supervision Task Sign-Off    Ironworkers: |
| 110                         | FIG. 10A  |

Name:
Company:
Location:
Foreman:
Signature:
Day Shift: \_\_ Night Shift:
Safety Dept. / Loss Management
DO NOT REMOVE

120

FIG. 10B




FIG. 11

